

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

1246
West
> 1
1.616 mi.
8534 ft.

**TRANSFORMER MANHOLE 863
MANHATTAN AVE /LAUREL AVE
BROOKLYN, NY**

**NY Spills S109371911
N/A**

**Relative:
Higher**

**Actual:
0 ft.**

SPILLS:

Name: TRANSFORMER MANHOLE 863
Address: MANHATTAN AVE /LAUREL AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0807245 / 2008-10-20
Facility ID: 0807245
Facility Type: ER
DER Facility ID: 353859
Site ID: 404584
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2008-09-27

Investigator: asnagi
Referred To: Not reported
Reported to Dept: 2008-09-27
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Not reported
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2008-09-27
Spill Record Last Update: 2008-10-20
Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ERT DESK
DEC Memo: "10/20/08 - See eDocs for Con Ed report detailing cleanup and closure. "

Remarks: "1 gallon of Unknown oil on 200 gallons of water/contained to manhole and clean up in progress."

All Materials:

Site ID: 404584
Operable Unit ID: 1161232
Operable Unit: 01
Material ID: 2152426
Material Code: 9999
Material Name: other - Unknown Oil
Case No.: Not reported
Material FA: Other
Quantity: Not reported
Units: G
Recovered: Not reported
Oxygenate: Not reported